

**BEAUFORT COUNTY
HISTORIC SITES SURVEY - 1997**

INTENSIVE LEVEL BUILDING INVENTORY FORM

Statewide Survey Site Form
State Historic Preservation Office
South Carolina Department of Archives and History
Columbia, SC

Site Number: U- 13 - 430
Access County Site #
USGS Quad: 290 Laurel Bay
Doc. Level: Intensive Level-Building

Historic name(s): Burlington Plantation Map Ref.: _____ Tax Number: R100 024 0042 0000
Common name(s): _____ City Block Ref.: _____ Island: _____
Address/location: off Joe Frazier Road City/Vicinity of (vic.) _____
Date: 1920 ca. Alteration date: _____
Ownership: 1. private 2. city 3. county 4. state 5. federal 6. unknown
Category: 1. building 2. site 3. structure 4. object
Historic use(s): Multiple dwelling Current uses: Abandoned

National Register Status: _____ Date: _____ Listing Name: _____ NRIS # _____

SHPO Determination: District: Contributing Non-contributing Potential: _____

Consultant Recommendation: _____

Previous Survey: _____ Reference: _____ Notes: _____
 H.A.B.S. Other.. _____
 Feiss-Wright (1969) _____
 Historic Resources of the Lowcountry (1979) _____
 Milner Historic District Inventory (1979) _____
 A Guide to Historic Beaufort (1995 ed.) _____

Photograph:



Photographs:

- prints
- slides
- negatives

Date: 5/7/97
Recorder: B. Harvey, Brockington & Assoc.

Roll # Neg. View of:
H-11 20 ne oblique

Style: Folk: massed-plan, side gabled Commercial Form: _____

Core Shape: rectangular Stories: 1 story Construction: frame

Roof: Shape: gable (lateral) Material: composition shingle

Chimney: Type: exterior Material: brick

Exterior Walls: weatherboard

Windows: single Type: double hung Pane Config.: open windows with insect screening stapled to frames

Doors: single Foundation: concrete piling

Porch Height: _____ Porch Width: _____ Porch Roof Shape: _____

Porch Details: _____ Decorative Elements: _____

Outbuildings: none visible Interior Features: _____

Number of Related Resources: _____


Surroundings: rural Acreage: _____ Quadrangle: Laurel Bay

Alterations: Alteration date: _____ Integrity: good Condition: deteriorated

Description: Long narrow building, facade features 8 bays (6 windows and 2 single doors). Facade still stands, but rear has collapsed. Returned eaves on gable ends.

Historical Data:

Sketch:



Site Number: **U - 13 - 430**

Informant/
Bibliography: