

**BEAUFORT COUNTY
HISTORIC SITES SURVEY – 1997**

Statewide Survey Site Form
State Historic Preservation Office
South Carolina Department of Archives and History
Columbia, SC

INTENSIVE LEVEL BUILDING INVENTORY FORM

Site Number: U - 13 - 483

Brockington Associates, Inc. • Brooker Architectural Design Consultants
Historic Beaufort Foundation • Preservation Consultants, Inc.

USGS Quad: 470 Sheldon
Doc. Level: Intensive Level - Building

Historic name(s): Myrtle Grove Plantation

Tax Number: 2700 018 000 0010 0000

Common name(s): Oak Grove Plantation

Address/location: William A. Campbell Road City/Vicinity of (vic.) Sheldon vic.

Date: 1922 Alteration date: _____

Ownership: 1. private 2. city 3. county 4. state 5. federal 6. unknown

Category: 1. building 2. site 3. structure 4. object

Historic use(s): single dwelling Current uses: abandoned

National Register Status:
Action: _____ Date: _____ Listing Name: _____ NRIS # _____

Local Designation: _____

Potential: _____

Source of Evaluation: _____ Number of Related Resources: _____

Previous Survey: _____ Reference: _____

Photograph:



Photographs:
 prints
 slides
 negatives

Date: 9/12/97
Recorder: B. Harvey, Brockington & Assoc.


Roll # _____ Neg. View of: _____
H-21 11 west elevation

Site Number: U - - 483
 Style: Colonial Revival Commercial Form: _____
 Core Shape: rectangular Stories: 2 stories Construction: frame
 Roof: Shape: gable (lateral) Material: composition shingle
 Chimney: Type: exterior Material: brick
 Exterior Walls: synthetic siding
 Windows: single Type: casement Pane Config.: _____
 Doors: single Foundation: brick
 Porch Height: _____ Porch Width: full facade Porch Roof Shape: shed
 Porch Details: supports on pedestals Decorative Elements: _____
 insect screening _____
 aluminum awning extending from porch _____
 Outbuildings: none Interior Features: _____
 Surroundings: plantation Acreage: _____ Quadrangle: Sheldon
 Alterations: Alteration date: _____ Integrity: fair Condition: good

Description: Five bay facade with a central door. Two tall casement windows on each side of the central door. Semi-circular brick steps leading to porch. Openwork brick fence surrounds front yard.

Historical Data: Built by grandfather of present owner.

Sketch:



Informant/
 Bibliography:

NORTH