

**BEAUFORT COUNTY
HISTORIC SITES SURVEY - 1997**

INTENSIVE LEVEL BUILDING INVENTORY FORM

Statewide Survey Site Form
State Historic Preservation Office
South Carolina Department of Archives and History
Columbia, SC

Site Number: U- 13 - 0013
Access County Site #

USGS Quad: 182 Frogmore
Doc. Level: Intensive Level-Building

Historic name(s): Corner Packing Shed Map Ref.: _____ Tax Number: R300 016 000 0130 0000
Common name(s): _____ City Block Ref.: _____ Island: St. Helena Is.
Address/location: 875 Sea Island Parkway City/Vicinity of (vic.) St. Helena Island
Date: 1930 ca. Alteration date: _____
Ownership: 1. private 2. city 3. county 4. state 5. federal 6. unknown
Category: 1. building 2. site 3. structure 4. object
Historic use(s): commercial Current uses: abandoned

National Register Status: _____ Date: _____ Listing Name: _____ NRIS # _____
listed individually in National Register 10/6/88 TheCorner Packing Shed

SHPO Determination: District: Contributing Non-contributing Potential: _____

Consultant Recommendation: _____

Previous Survey: _____ Reference: _____ Notes: _____
 H.A.B.S. Other.. _____
 Feiss-Wright (1969) _____
 Historic Resources of the Lowcountry (1979) _____
 Milner Historic District Inventory (1979) _____
 A Guide to Historic Beaufort (1995 ed.) _____

Photograph:



Photographs:

- prints
- slides
- negatives

Date: 6/24/98
Recorder: B. Harvey, Brockington & Assoc.

Roll # Neg. View of:
1433 1 sw oblique

Style: _____ Commercial Form: _____

Core Shape: rectangular Stories: 1 story Construction: frame

Roof: Shape: gable (end to front) Material: raised seam metal

Chimney: Type: _____ Material: _____

Exterior Walls: weatherboard

Windows: _____ Type: _____ Pane Config.: _____

Doors: _____ Foundation: _____

Porch Height: _____ Porch Width: _____ Porch Roof Shape: _____

Porch Details: _____ Decorative Elements: _____

Outbuildings: none Interior Features: _____

Number of Related Resources: _____


Surroundings: rural crossroads community Acreage: 1 Quadrangle: Frogmore

Alterations: _____ Alteration date: _____ Integrity: good Condition: fair

Description: Long rectangular shed, gable aisle with shed roof porches on each side. Lower level siding removed, wooden frame supports open; area under gable enclosed in weatherboard. Single door opening in gable.

Historical Data: Served as the packing shed for area truck farming.

Sketch:



Site Number: U - 13 - 0013