

**BEAUFORT COUNTY
HISTORIC SITES SURVEY - 1997**

INTENSIVE LEVEL BUILDING INVENTORY FORM

Statewide Survey Site Form
State Historic Preservation Office
South Carolina Department of Archives and History
Columbia, SC

Site Number: U- 13 - 15
Access County Site #

USGS Quad: 182 Frogmore
Doc. Level: Intensive Level-Building

Historic name(s): Croft Praise House Map Ref.: _____ Tax Number: R300 006 000 030A 0000

Common name(s): _____ City Block Ref.: _____ Island: St. Helena Is.

Address/location: Eddings Point Road City/Vicinity of (vic.) St. Helena Island

Date: 1900 ca. Alteration date: _____

Ownership: 1. private 2. city 3. county 4. state 5. federal 6. unknown

Category: 1. building 2. site 3. structure 4. object

Historic use(s): Praise House Current uses: religious

National Register Status: _____ Date: _____ Listing Name: _____ NRIS # _____
determined eligible-owner objection 5/26/89

SHPO Determination: District: Contributing Non-contributing Potential: _____

Consultant Recommendation: _____

Previous Survey:	Reference:	Notes:
<input type="checkbox"/> H.A.B.S.	<input type="checkbox"/> Other..	
<input type="checkbox"/> Feiss-Wright (1969)		
<input type="checkbox"/> Historic Resources of the Lowcountry (1979)		
<input type="checkbox"/> Milner Historic District Inventory (1979)		
<input type="checkbox"/> A Guide to Historic Beaufort (1995 ed.)		

Photograph:



Photographs:

- prints
- slides
- negatives

Date: 9/10/97
Recorder: B. Harvey, Brockington & Assoc.

Roll #	Neg.	View of:
<u>H-19</u>	<u>3</u>	<u>sw oblique</u>
_____	_____	_____
_____	_____	_____

Style: Folk: gable front Commercial Form: _____

Core Shape: rectangular Stories: 1 story Construction: frame

Roof: Shape: gable (end to front) Material: composition shingle

Chimney: Type: _____ Material: _____

Exterior Walls: plywood

Windows: single Type: fixed Pane Config.: _____

Doors: single Foundation: concrete block piers

Porch Height: _____ Porch Width: _____ Porch Roof Shape: _____

Porch Details: _____ Decorative Elements: _____

Outbuildings: _____ Interior Features: _____

Number of Related Resources: _____


Surroundings: rural Acreage: _____ Quadrangle: Frogmore

Alterations: Alteration date: _____ Integrity: fair Condition: good

Description: Small (10x25) front building, off center front wooden panel door. Two windows on each long side, one with a wooden casement, the other a 6-pane fixed window.

Historical Data:

Sketch:



Site Number: U - 13 - 15

Informant/ Bibliography: Robert Middleton, interview, 9/97