

**BEAUFORT COUNTY
HISTORIC SITES SURVEY - 1997**

INTENSIVE LEVEL BUILDING INVENTORY FORM

Statewide Survey Site Form
State Historic Preservation Office
South Carolina Department of Archives and History
Columbia, SC

Site Number: U- 13 - 18
Access County Site #

USGS Quad: 182 Frogmore
Doc. Level: Intensive Level-Building

Historic name(s): Eddings Point Community Praise House Map Ref.: _____ Tax Number: R300.010.000.0046.0000
Common name(s): _____ City Block Ref.: _____ Island: St. Helena Is.
Address/location: 219 Eddings Point Road City/Vicinity of (vic.) St. Helena Island
Date: 1900 ca. Alteration date: 1940 ca., 1970 ca.
Ownership: 1. private 2. city 3. county 4. state 5. federal 6. unknown
Category: 1. building 2. site 3. structure 4. object
Historic use(s): Praise House Current uses: religious

National Register Status: _____ Date: _____ Listing Name: _____ NRIS # _____
listed individually in National Register 5/19/89 Eddings Point Comm. Praise House

SHPO Determination: District: Contributing Non-contributing Potential: _____

Consultant Recommendation: _____

Previous Survey: _____ Reference: _____ Notes: _____
 H.A.B.S. Other.. _____
 Feiss-Wright (1969) _____
 Historic Resources of the Lowcountry (1979) _____
 Milner Historic District Inventory (1979) _____
 A Guide to Historic Beaufort (1995 ed.) _____

Photograph:



Photographs:
 prints
 slides
 negatives

Date: 9/10/97
Recorder: B. Harvey, Brockington & Assoc.

Roll # Neg. View of:
H-19 8 ne oblique

Style: Folk: gable front Commercial Form: _____

Core Shape: rectangular Stories: 1 story Construction: frame
Roof: Shape: gable (end to front) Material: composition shingle

Chimney: Type: _____ Material: _____

Exterior Walls: weatherboard

Windows: single Type: wooden casement window in front section, double hung window in rear addition Pane 6/6 Config.: _____

Doors: single Foundation: concrete block piers

Porch Height: _____ Porch Width: _____ Porch Roof Shape: _____

Porch Details: _____ Decorative Elements: _____

Outbuildings: none Interior Features: _____

Number of Related Resources: _____


Surroundings: rural Acreage: _____ Quadrangle: Frogmore

Alterations: Alteration date: 1940 ca., 1970 ca. Integrity: fair Condition: fair
Rear section has been added; new front door.

Description: Small rectangular building, c. 15X20. Off-center front door, two windows on each long side.

Historical Data:

Sketch:



Site Number: U - 13 - 18

Informant/
Bibliography: