

**BEAUFORT COUNTY
HISTORIC SITES SURVEY - 1997**

INTENSIVE LEVEL BUILDING INVENTORY FORM

Statewide Survey Site Form
State Historic Preservation Office
South Carolina Department of Archives and History
Columbia, SC

Site Number: U- 13 - 248.09
Access County Site #

USGS Quad: 470 Sheldon
Doc. Level: Intensive Level-Building

Historic name(s): Supervisor's Home and Office Map Ref.: _____ Tax Number: R100 012 000 0010 0000

Common name(s): _____ City Block Ref.: _____ Island: _____

Address/location: Seabrook Drive at railroad tracks City/Vicinity of (vic.) Seabrook

Date: 1945 ca. Alteration date: _____

Ownership: 1. private 2. city 3. county 4. state 5. federal 6. unknown

Category: 1. building 2. site 3. structure 4. object

Historic use(s): single dwelling Current uses: office

National Register Status: _____ Date: _____ Listing Name: _____ NRIS # _____
listed as part of NR Historic District 7/25/97 McLeod Farmstead

SHPO Determination: District: Contributing Non-contributing Potential: _____

Consultant Recommendation: _____

Previous Survey: _____ Reference: _____ Notes: _____
 H.A.B.S. Other.. _____
 Feiss-Wright (1969) _____
 Historic Resources of the Lowcountry (1979) _____
 Milner Historic District Inventory (1979) _____
 A Guide to Historic Beaufort (1995 ed.) _____

Photograph:



Photographs:

- prints
- slides
- negatives

Date: 2/12/97

Recorder: B. Harvey, Brockington & Assoc.

Roll #	Neg.	View of:
<u>H-4</u>	<u>19</u>	<u>se oblique</u>

Style: Folk: gable front Commercial Form: _____

Core Shape: rectangular Stories: 1 story Construction: frame

Roof: Shape: gable (end to front) Material: composition shingle

Chimney: Type: central Material: brick

Exterior Walls: _____

Windows: double Type: double hung Pane 6/6
Config.: _____

Doors: single Foundation: brick piers

Porch Height: _____ Porch Width: _____ Porch Roof Shape: _____

Porch Details: _____
Decorative Elements: _____

Outbuildings: none Interior Features: _____

Number of Related Resources: 13


Surroundings: rural community Acreage: _____ Quadrangle: Sheldon

Alterations: Alteration date: _____ Integrity: good Condition: good

Description: Front gable with 3 bays, 3 rooms deep.

Historical Data: Built by father of current owner, immediately after return home from World War II. Housed the supervisor for the McLeod truck farming operation. The McLeod farm was one of the most important of the rapid increase of truck farms throughout the South Carolina Lowcountry. The farm began in 1884 when William H. McLeod and his son, Claudius E. McLeod bought land along the west side of the new Port Royal and Augusta Railroad.

Sketch:



Site Number: U - 13 - 248.09

Informant/
Bibliography: Claude McLeod, current owner; Natalie Harvey, NRHP nomination, 1996.