

**BEAUFORT COUNTY
HISTORIC SITES SURVEY - 1997**

INTENSIVE LEVEL BUILDING INVENTORY FORM

Statewide Survey Site Form
State Historic Preservation Office
South Carolina Department of Archives and History
Columbia, SC

Site Number: U- 13 - 26.03
Access County Site #
USGS Quad: 445 Saint Phillips Island
Doc. Level: Intensive Level-Building

Historic name(s): Frogmore Plantation Map Ref.: _____ Tax Number: R300 023 000 0231 0000
Common name(s): _____ City Block Ref.: _____ Island: St. Helena Is.
Address/location: 59 Sassafras Drive City/Vicinity of (vic.): St. Helena Island
Date: 1930 ca. Alteration date: _____
Ownership: 1. private 2. city 3. county 4. state 5. federal 6. unknown
Category: 1. building 2. site 3. structure 4. object
Historic use(s): single dwelling Current uses: _____

National Register Status: _____ Date: _____ Listing Name: _____ NRIS # _____

SHPO Determination: District: Contributing Non-contributing Potential: _____

Consultant Recommendation: _____

Previous Survey: H.A.B.S. Other.. _____ Reference: _____ Notes: _____
 Feiss-Wright (1969) _____
 Historic Resources of the Lowcountry (1979) _____
 Milner Historic District Inventory (1979) _____
 A Guide to Historic Beaufort (1995 ed.) _____

Photograph:



Photographs:
 prints
 slides
 negatives

Date : _____
Recorder: B. Harvey, Brockington & Assoc.

Roll # Neg. View of:
H-16 13A _____

Style: Folk: gable front Commercial Form: _____

Core Shape: rectangular Stories: 1 story Construction: _____

Roof: Shape: gable (end to front) Material: composition shingle

Chimney: Type: _____ Material: _____

Exterior Walls: weatherboard

Windows: triple Type: double hung Pane 6/6
single Config.: _____

Doors: single Foundation: slab construction

Porch Height: 1 story Porch Width: over 1 bay, less than full Porch Roof Shape: shed
 Porch Details: posts Decorative Elements: _____

Outbuildings: _____ Interior Features: _____

Number of Related Resources: _____


Surroundings: plantation complex Acreage: _____ Quadrangle: Saint Phillips Island

Alterations: Alteration date: _____ Integrity: good Condition: good

Description: narrow one-bay small house with central front door. Small section apparently added to the rear; door at end features segmental arch door cap with lattice sides.

Historical Data:

Sketch:



Site Number: U - 13 - 26.03

Informant/
Bibliography: