

**BEAUFORT COUNTY
HISTORIC SITES SURVEY - 1997**

INTENSIVE LEVEL BUILDING INVENTORY FORM

Statewide Survey Site Form
State Historic Preservation Office
South Carolina Department of Archives and History
Columbia, SC

Site Number: U- 13 - 29.01
Access County Site #
USGS Quad: 442 St Helena Sound
Doc. Level: Intensive Level-Building

Historic name(s): Hunting Island Lighthouse Complex Map Ref.: _____ Tax Number: R300 011 000 0010 0000
Common name(s): Oil storage house City Block Ref.: _____ Island: St. Helena Is.
Address/location: Hunting Island State Park City/Vicinity of (vic.) St. Helena Island vic.
Date: 1889 ca. Alteration date: _____
Ownership: 1. private 2. city 3. county 4. state 5. federal 6. unknown
Category: 1. building 2. site 3. structure 4. object
Historic use(s): storage Current uses: visitor center


National Register Status: _____ Date: _____ Listing Name: _____ NRIS # _____
listed individually in National Register 6/5/70 Hunting Island State Park Lighthouse

SHPO Determination: District: Contributing Non-contributing Potential: _____

Consultant Recommendation: _____

Previous Survey: _____ Reference: _____ Notes: _____
 H.A.B.S. Other, _____
 Feiss-Wright (1969) _____
 Historic Resources of the Lowcountry (1979) _____
 Milner Historic District Inventory (1979) _____
 A Guide to Historic Beaufort (1995 ed.) _____

Photograph:



Photographs:
 prints
 slides
 negatives

Date: 7/16/97
Recorder: B. Harvey, Brockington & Assoc.

Roll # Neg. View of:
H-18 11 se oblique

Style: Folk: gable front Commercial Form: _____

Core Shape: rectangular Stories: 1 story Construction: masonry

Roof: Shape: gable (end to front) Material: composition shingle

Chimney: Type: _____ Material: _____

Exterior Walls: brick

Windows: single Type: double hung Pane 1/1
 Config.: _____

Doors: single Foundation: brick

Porch Height: _____ Porch Width: _____ Porch Roof Shape: _____

Porch Details: _____

Outbuildings: _____

Decorative Elements: _____

Interior Features: _____

Number of Related Resources: _____


Surroundings: state park Acreage: _____ Quadrangle: St Helena Sound

Alterations: Alteration date: _____ Integrity: good Condition: excellent

Description: Small (ca. 10 x 12) brick building with a one room interior. Central door on front; one single modern window on each side wall.

Historical Data: Served as oil storage house, immediately adjacent to the Hunting Island Lighthouse. Built about 1889, when the lighthouse was moved to its present location.

Sketch:



Site Number: **U - 13 - 29.01**