

**BEAUFORT COUNTY
HISTORIC SITES SURVEY - 1997**

INTENSIVE LEVEL BUILDING INVENTORY FORM

Statewide Survey Site Form
State Historic Preservation Office
South Carolina Department of Archives and History
Columbia, SC

Site Number: U- 13 - 29.02
Access County Site #
USGS Quad: 442 St Helena Sound
Doc. Level: Intensive Level-Building

Historic name(s): Hunting Island Lighthouse Complex Map Ref.: _____ Tax Number: R300 011 000 0010 0000
Common name(s): _____ City Block Ref.: _____ Island: St. Helena Is.
Address/location: Hunting Island State Park City/Vicinity of (vic.) St. Helena Island vic.
Date: 1889 ca. Alteration date: _____
Ownership: 1. private 2. city 3. county 4. state 5. federal 6. unknown
Category: 1. building 2. site 3. structure 4. object
Historic use(s): storage Current uses: visitor center

National Register Status: _____ Date: _____ Listing Name: _____ NRIS # _____
listed individually in National Register 6/5/70 Hunting Island State Park Lighthouse

SHPO Determination: District: Contributing Non-contributing Potential: _____

Consultant Recommendation: _____

Previous Survey: Reference: Notes:
 H.A.B.S. Other.. _____
 Feiss-Wright (1969) _____
 Historic Resources of the Lowcountry (1979) _____
 Milner Historic District Inventory (1979) _____
 A Guide to Historic Beaufort (1995 ed.) _____

Photograph:



Photographs:

- prints
- slides
- negatives

Date: 7/16/97
Recorder: B. Harvey, Brockington & Assoc.

Roll # Neg. View of:
H-18 10 nw oblique

Style: Folk: hall-and-parlor Commercial Form: _____

Core Shape: L-front-right Stories: 1 story Construction: frame

Roof: Shape: cross gable Material: composition shingle

Chimney: Type: _____ Material: _____

Exterior Walls: board & batten

Windows: _____ Type: _____ Pane Config.: _____

Doors: double Foundation: brick piers with brick fill

Porch Height: _____ Porch Width: _____ Porch Roof Shape: _____

Porch Details: _____ Decorative Elements: exposed rafter tails

Outbuildings: _____ Interior Features: _____

Number of Related Resources: _____

Surroundings: part of lighthouse complex Acreage: _____ Quadrangle: St Helena Sound

Alterations: Alteration date: _____ Integrity: good Condition: excellent

Description: Small, one or two room building. Paired doors on long side, with new wooden steps leading to main floor. Exposed, shaped rafter tails.

Historical Data: Part of the Hunting Island Lighthouse complex, built about 1889, when the lighthouse was moved to its present location.

Sketch:

NORT
H

Site Number: U - 13 - 29.02

Informant/ Bibliography: Mike Hyatt, Rowena Nylund, Stan Hutto, Hunting Island Sate Park Visitors Guide, 1993.