

**BEAUFORT COUNTY
HISTORIC SITES SURVEY - 1997**

INTENSIVE LEVEL BUILDING INVENTORY FORM

Statewide Survey Site Form
State Historic Preservation Office
South Carolina Department of Archives and History
Columbia, SC

Site Number: U- 13 - 343
Access County Site #

USGS Quad: 442 St Helena Sound
Doc. Level: Intensive Level-Building

Historic name(s): CCC Mess Hall Map Ref.: _____ Tax Number: R300 011 000 0010 0000
Common name(s): Maintenance City Block Ref.: _____ Island: Hunting Is.
Address/location: 2555 Shed Road City/Vicinity of (vic.) Hunting Island
Date: 1938 ca. Alteration date: _____
Ownership: 1. private 2. city 3. county 4. state 5. federal 6. unknown
Category: 1. building 2. site 3. structure 4. object
Historic use(s): dining hall Current uses: maintenance shed

National Register Status: _____ Date: _____ Listing Name: _____ NRIS # _____

SHPO Determination: District: Contributing Non-contributing Potential: _____

Consultant Recommendation: potential for local designation

Previous Survey: H.A.B.S. Other.. _____ Reference: _____ Notes: _____
 Feiss-Wright (1969) _____
 Historic Resources of the Lowcountry (1979) _____
 Milner Historic District Inventory (1979) _____
 A Guide to Historic Beaufort (1995 ed.) _____

Photograph:



Photographs:
 prints
 slides
 negatives

Date: 7/16/97
Recorder: B. Harvey, Brockington & Assoc.

Roll # Neg. View of:
H-18 7 se oblique

Style: Folk: gable front Commercial Form: _____

Core Shape: rectangular Stories: 1 story Construction: frame

Roof: Shape: gable (end to front) Material: raised seam metal

Chimney: Type: _____ Material: _____

Exterior Walls: weatherboard

Windows: single Type: fixed Pane 9 pane windows
 Config.: _____

Doors: single Foundation: timber piers with diagonal brackets
double

Porch Height: _____ Porch Width: _____ Porch Roof Shape: _____

Porch Details: _____

Outbuildings: none Interior Features: _____


Number of Related Resources: _____

Surroundings: campsite Acreage: 1 Quadrangle: St Helena Sound

Alterations: Alteration date: _____ Integrity: good Condition: good

Description: Simple front gable, 1 bay wide building with a central double door under the gable; single door on left side. Overhanging eaves supported by simple brackets. Unique feature--diagonal brackets extending from ground level of foundation piers upward to bottom plate.

Historical Data: Served as mess hall for Civilian Conservation Corps personnel creating Hunting Island State Park, circa 1938.



Site Number: U - 13 - 343

Informant/ Bibliography: Jeff Atkins, Ranger, personal communication, 7/16/97