

**BEAUFORT COUNTY
HISTORIC SITES SURVEY - 1997**

INTENSIVE LEVEL BUILDING INVENTORY FORM

Statewide Survey Site Form
State Historic Preservation Office
South Carolina Department of Archives and History
Columbia, SC

Site Number: U- 13 - 354
Access County Site #
USGS Quad: 025 Beaufort
Doc. Level: Intensive Level-Building

Historic name(s): Goings House Map Ref.: _____ Tax Number: R100 028 000 156A 0000
Common name(s): _____ City Block Ref.: _____ Island: _____
Address/location: ^{368A} 300 Parris Island Gateway City/Vicinity of (vic.) Beaufort vic.
Date: 1900 Alteration date: 1981
Ownership: 1. private 2. city 3. county 4. state 5. federal 6. unknown
Category: 1. building 2. site 3. structure 4. object
Historic use(s): single dwelling Current uses: single dwelling

National Register Status: _____ Date: _____ Listing Name: _____ NRIS # _____

SHPO Determination: District: Contributing Non-contributing Potential: local designation

Consultant Recommendation: _____

Previous Survey: _____ Reference: _____ Notes: _____
 H.A.B.S. Other.. _____
 Feiss-Wright (1969) _____
 Historic Resources of the Lowcountry (1979) _____
 Milner Historic District Inventory (1979) _____
 A Guide to Historic Beaufort (1995 ed.) _____

Photograph:



Photographs:

- prints
- slides
- negatives

Date: 3/11/97
Recorder: B. Harvey, Brockington & Assoc.

Roll # Neg. View of:
H-8 8 sw oblique

Style: Folk I-house Commercial Form: _____

Core Shape: rectangular Stories: 2 stories Construction: frame

Roof: Shape: gable (end to front) Material: rolled roofing

Chimney: Type: exterior Material: brick

Exterior Walls: _____

Windows: single Type: double hung Pane 6/6
 Config.: _____

Doors: single Foundation: brick piers

Porch Height: 2 or more with tiers Porch Width: full facade Porch Roof Shape: shed

Porch Details: posts Decorative Elements: _____

Outbuildings: garage Interior Features: _____


Number of Related Resources: _____

Surroundings: rural Acreage: _____ Quadrangle: Beaufort

Alterations: Alteration date: 1981 Integrity: fair Condition: good
 Restored 1981; resided with particle board, foundation filled in, side windows removed and replace with square 1-pane windows.

Description: 2-story I house with ell at back. 6 bays, door is third from left. 5 bays on second floor, door in center.

Historical Data: Served as Bachelor Officers Quarters during WWII. Long time house of Goings family, who operated a store in Burton.



Site Number: U - 13 - 354

Informant/ Bibliography: Current owner.