

**BEAUFORT COUNTY
HISTORIC SITES SURVEY - 1997**

INTENSIVE LEVEL BUILDING INVENTORY FORM

Statewide Survey Site Form
State Historic Preservation Office
South Carolina Department of Archives and History
Columbia, SC

Site Number: U- 13 - 38.04
Access County Site #
USGS Quad: 182 Frogmore
Doc. Level: Intensive Level-Building

Historic name(s): Penn Center Historic District Map Ref.: _____ Tax Number: R300 016 000 0094 0000
Common name(s): garage City Block Ref.: _____ Island: St. Helena Is.
Address/location: 38 Penn Center Circle City/Vicinity of (vic.) St. Helena Island
Date: 1920 ca. Alteration date: _____
Ownership: 1. private 2. city 3. county 4. state 5. federal 6. unknown
Category: 1. building 2. site 3. structure 4. object
Historic use(s): barn Current uses: garage

National Register Status: _____ Date: _____ Listing Name: _____ NRIS # _____
listed as part of NR Historic District 9/9/74 Penn Center Historic District

SHPO Determination: District: Contributing Non-contributing Potential: _____

Consultant Recommendation: _____

Previous Survey: _____ Reference: _____ Notes: _____
 H.A.B.S. Other.. _____
 Feiss-Wright (1969) _____
 Historic Resources of the Lowcountry (1979) _____
 Milner Historic District Inventory (1979) _____
 A Guide to Historic Beaufort (1995 ed.) _____

Photograph:



Photographs:

- prints
- slides
- negatives

Date: 7/10/97
Recorder: B. Harvey, Brockington & Assoc.

Roll # Neg. View of:
H-17 1 northeast oblique

Style: _____ Commercial Form: _____

Core Shape: rectangular Stories: 1 story Construction: frame

Roof: Shape: gable (lateral) Material: raised seam metal

Chimney: Type: _____ Material: _____

Exterior Walls: weatherboard

Windows: single Type: fixed Pane Config.: _____

Doors: no doors; open garage bays only Foundation: slab construction

Porch Height: _____ Porch Width: _____ Porch Roof Shape: _____

Porch Details: _____ Decorative Elements: _____

Outbuildings: _____ Interior Features: _____

Number of Related Resources: _____


Surroundings: campus Acreage: _____ Quadrangle: Frogmore

Alterations: Alteration date: _____ Integrity: good Condition: good

Description: 7-bay wooden garage with no doors; fixed window on side.

Historical Data: Part of Penn Center farm complex.

Sketch:



Site Number: U - 13 - 38.04

Informant/
Bibliography:

NRHP Form, "Penn Center Historic District," Penn's Campus Tour Guide," unpublished ms. located in NRHP files.