

**BEAUFORT COUNTY
HISTORIC SITES SURVEY - 1997**

INTENSIVE LEVEL BUILDING INVENTORY FORM

Statewide Survey Site Form
State Historic Preservation Office
South Carolina Department of Archives and History
Columbia, SC

Site Number: U- 13 - 388
Access County Site #
USGS Quad: 025 Beaufort
Doc. Level: Reconnaissance Level

Historic name(s): Israelite Church Map Ref.: _____ Tax Number: R200 010 000 0044 0000
Common name(s): _____ City Block Ref.: _____ Island: Lady's Is.
Address/location: 29 Israelite Church Road City/Vicinity of (vic.): Lady's Island
Date: 1900 Alteration date: 1980?
Ownership: 1. private 2. city 3. county 4. state 5. federal 6. unknown
Category: 1. building 2. site 3. structure 4. object
Historic use(s): Church Current uses: Church

National Register Status: _____ Date: _____ Listing Name: _____ NRIS # _____

SHPO Determination: District: Contributing Non-contributing Potential: _____

Consultant Recommendation: _____

Previous Survey:	Reference:	Notes:
<input type="checkbox"/> H.A.B.S.	<input type="checkbox"/> Other.. _____	_____
<input type="checkbox"/> Feiss-Wright (1969)	_____	_____
<input type="checkbox"/> Historic Resources of the Lowcountry (1979)	_____	_____
<input type="checkbox"/> Milner Historic District Inventory (1979)	_____	_____
<input type="checkbox"/> A Guide to Historic Beaufort (1995 ed.)	_____	_____

Photograph:



Photographs:

- prints
- slides
- negatives

Date: 4/30/97
Recorder: B. Harvey, Brockington & Assoc.

Roll #	Neg.	View of:
<u>H-9</u>	<u>23</u>	<u>se oblique</u>
_____	_____	_____
_____	_____	_____
_____	_____	_____

Style: Folk: gable front Commercial Form: _____

Core Shape: L-rear-left Stories: 1 story Construction: frame

Roof: Shape: gable (end to front) Material: composition shingle

Chimney: Type: _____ Material: _____

Exterior Walls: _____

Windows: single Type: double hung Pane 6/6

Doors: double Foundation: brick

Porch Height: 1 story Porch Width: full facade Porch Roof Shape: gable

Porch Details: posts Decorative Elements: _____

Outbuildings: springhouse Interior Features: _____

Number of Related Resources: _____


Surroundings: rural Acreage: _____ Quadrangle: Beaufort

Alterations: Alteration date: 1980? Integrity: fair Condition: excellent

Brick veneer appears added, one- or two-room addition to left side rear..

Description: Front gabled church with small steeple at center front. Shallow gable roof; porch roof projects below eave line at the same pitch. plain brick piers support porch. Exposed rafter tails. Wing extends to left from rear. Brick porch and steps. Facade features 3 bays with a central door; windows surmounted by arched transoms.

Historical Data:



Site Number: U - 13 - 388

Informant/ Bibliography: Beaufort County R.M.C.