

**BEAUFORT COUNTY
HISTORIC SITES SURVEY - 1997**

INTENSIVE LEVEL BUILDING INVENTORY FORM

Statewide Survey Site Form
State Historic Preservation Office
South Carolina Department of Archives and History
Columbia, SC

Site Number: U- 13 - 409
Access County Site #
USGS Quad: 442 St Helena Sound
Doc. Level: Intensive Level-Building

Historic name(s): _____ Map Ref.: _____ Tax Number: R300.029.000.0023.0000
Common name(s): _____ City Block Ref.: _____ Island: St. Helena Is.
Address/location: **570 Lands End Road** City/Vicinity of (vic.) St. Helena Island
Date: 1945 ca. Alteration date: _____
Ownership: 1. private 2. city 3. county 4. state 5. federal 6. unknown
Category: 1. building 2. site 3. structure 4. object
Historic use(s): commercial Current uses: commercial

National Register Status: _____ Date: _____ Listing Name: _____ NRIS # _____

SHPO Determination: District: Contributing Non-contributing Potential: _____

Consultant Recommendation: _____

Previous Survey: _____ Reference: _____ Notes: _____
 H.A.B.S. Other.. _____
 Feiss-Wright (1969) _____
 Historic Resources of the Lowcountry (1979) _____
 Milner Historic District Inventory (1979) _____
 A Guide to Historic Beaufort (1995 ed.) _____

Photograph:



Photographs:
 prints
 slides
 negatives

Date: 7/3/97
Recorder: B. Harvey, Brockington & Assoc.

Roll # Neg. View of:
H-15 6 ne oblique

Style: Folk: gable front _____ Commercial Form: 1-part commercial block _____

Core Shape: rectangular _____ Stories: 1 story _____ Construction: masonry _____

Roof: Shape: gable (end to front) _____ Material: composition shingle _____

Chimney: Type: flue _____ Material: brick _____

Exterior Walls: concrete block _____

Windows: display _____ Type: covered in wooden shutters _____ Pane not visible _____
 Config.: _____

Doors: double _____ Foundation: not visible _____

Porch Height: 1 story _____ Porch Width: over 1 bay, less than full _____ Porch Roof Shape: shed _____

Porch Details: chamfered posts _____ Decorative Elements: _____

Outbuildings: garage _____ Interior Features: _____

Number of Related Resources: _____


Surroundings: rural _____ Acreage: 1 _____ Quadrangle: St Helena Sound _____

Alterations: Alteration date: _____ Integrity: fair _____ Condition: good _____
 Roof appears new. Cement block addition, 1-room on right side rear

Description: Small front gable store with steeply pitched roof. Three bay facade, central double doors with flanking small display windows, with hinged wooden shutters. Hopper windows at eave lines.

Historical Data:

Sketch:



Site Number: U - 13 - 409

Informant/
Bibliography: