

**BEAUFORT COUNTY
HISTORIC SITES SURVEY - 1997**

INTENSIVE LEVEL BUILDING INVENTORY FORM

Statewide Survey Site Form
State Historic Preservation Office
South Carolina Department of Archives and History
Columbia, SC

Site Number: U- 13 - 48.02
Access County Site #

USGS Quad: 445 Saint Phillips Island
Doc. Level: Intensive Level-Building

Historic name(s): Seaside Plantation/Fripp Plantation Map Ref.: _____ Tax Number: R300 023 000 136D 0000

Common name(s): _____ City Block Ref.: _____ Island: St. Helena Is.

Address/location: 1109 Seaside Plantation City/Vicinity of (vic.) St. Helena Island

Date: 1920 ca. Alteration date: _____

Ownership: 1. private 2. city 3. county 4. state 5. federal 6. unknown

Category: 1. building 2. site 3. structure 4. object

Historic use(s): silo Current uses: _____

National Register Status: _____ Date: _____ Listing Name: _____ NRIS # _____

SHPO Determination: District: Contributing Non-contributing Potential: _____

Consultant Recommendation: _____

Previous Survey:	Reference:	Notes:
<input type="checkbox"/> H.A.B.S.	<input type="checkbox"/> Other.. _____	_____
<input type="checkbox"/> Feiss-Wright (1969)	_____	_____
<input type="checkbox"/> Historic Resources of the Lowcountry (1979)	_____	_____
<input type="checkbox"/> Milner Historic District Inventory (1979)	_____	_____
<input type="checkbox"/> A Guide to Historic Beaufort (1995 ed.)	_____	_____

Photograph:



Photographs:

- prints
- slides
- negatives

Date: 7/3/97

Recorder: B. Harvey, Brockington & Assoc.

Roll #	Neg.	View of:
<u>H-16</u>	<u>5</u>	_____
_____	_____	_____
_____	_____	_____
_____	_____	_____

Style: _____ Commercial Form: _____

Core Shape: circular Stories: 3 or more stories Construction: masonry
Roof Shape: not visible Material: _____

Chimney: Type: _____ Material: _____

Exterior Walls: poured concrete

Windows: _____ Type: _____ Pane Config.: _____

Doors: _____ Foundation: _____

Porch Height: _____ Porch Width: _____ Porch Roof Shape: _____

Porch Details: _____ Decorative Elements: _____

Outbuildings: _____ Interior Features: _____

Number of Related Resources: _____


Surroundings: _____ Acreage: _____ Quadrangle: Saint Phillips Island

Alterations: _____ Alteration date: _____ Integrity: good Condition: good

Description: Round concrete silo adjacent to barn, at the rear of the plantation house

Historical Data:

Sketch:



Site Number: U - 13 - 48.02

Informant/ Bibliography: NHRP nomination, "Seaside Plantation"