

**BEAUFORT COUNTY
HISTORIC SITES SURVEY - 1997**

INTENSIVE LEVEL BUILDING INVENTORY FORM

Statewide Survey Site Form
State Historic Preservation Office
South Carolina Department of Archives and History
Columbia, SC

Site Number: U- 13 - 480
Access County Site #
USGS Quad: 442 St Helena Sound
Doc. Level: Intensive Level-Building

Historic name(s): Coffin Point Praise House Map Ref.: _____ Tax Number: R300 012 000 0055
Common name(s): _____ City Block Ref.: _____ Island: St. Helena Is.
Address/location: 61 Coffin Point Road City/Vicinity of (vic.) St. Helena Island
Date: 1900 ca. Alteration date: 1990 ca.
Ownership: 1. private 2. city 3. county 4. state 5. federal 6. unknown
Category: 1. building 2. site 3. structure 4. object
Historic use(s): Praise House Current uses: religious

National Register Status: _____ Date: _____ Listing Name: _____ NRIS # _____
determined eligible-owner objection 5/26/89

SHPO Determination: District: Contributing Non-contributing Potential: _____

Consultant Recommendation: _____

Previous Survey: _____ Reference: _____ Notes: _____
 H.A.B.S. Other.. _____
 Feiss-Wright (1969) _____
 Historic Resources of the Lowcountry (1979) _____
 Milner Historic District Inventory (1979) _____
 A Guide to Historic Beaufort (1995 ed.) _____

Photograph:



Photographs:

- prints
- slides
- negatives

Date: 9/10/97
Recorder: B. Harvey, Brockington & Assoc.


Roll # Neg. View of:
H-19 23

Style: Folk: gable front _____ Commercial Form: _____
 Core Shape: rectangular _____ Stories: 1 story _____ Construction: frame _____
 Roof: Shape: gable (end to front) _____ Material: raised seam metal _____
 Chimney: Type: _____ Material: _____
 Exterior Walls: mix of weatherboard and hewn siding _____
 Windows: single _____ Type: fixed _____ Pane 4-pane fixed _____
 Config.: _____
 Doors: single _____ Foundation: concrete block piers _____
 Porch Height: _____ Porch Width: _____ Porch Roof Shape: _____
 Porch Details: _____ Decorative Elements: _____
 Outbuildings: none _____ Interior Features: _____
 Number of Related Resources: _____
 Surroundings: rural _____ Acreage: _____ Quadrangle: St Helena Sound _____
 Alterations: Alteration date: 1990 ca. _____ Integrity: good _____ Condition: good _____
 new wooden steps to central front door.

Description: Small (10x12) building with a central vertical panel door and two fixed windows on facade, one fixed window on each long side. Shallow front gable roof, exposed rafter tails.

Historical Data:

Sketch:



Site Number: U - 13 - 480

Informant/
 Bibliography: