

**BEAUFORT COUNTY
HISTORIC SITES SURVEY - 1997**

INTENSIVE LEVEL BUILDING INVENTORY FORM

Statewide Survey Site Form
State Historic Preservation Office
South Carolina Department of Archives and History
Columbia, SC

Site Number: U- 13 - 481.07
Access County Site #
USGS Quad: 470 Sheldon
Doc. Level: Intensive Level-Building

Historic name(s): Tomotley Plantation Map Ref.: _____ Tax Number: R700.0013.000.0001
Common name(s): _____ City Block Ref.: _____ Island: _____
Address/location: off Old Sheldon Road City/Vicinity of (vic.) Gardens Corner vic.
Date: 1910 ca. Alteration date: _____
Ownership: 1. private 2. city 3. county 4. state 5. federal 6. unknown
Category: 1. building 2. site 3. structure 4. object
Historic use(s): single dwelling Current uses: single dwelling

National Register Status: _____ Date: _____ Listing Name: _____ NRIS # _____

SHPO Determination: District: Contributing Non-contributing Potential: National Register District, Contributing

Consultant Recommendation: _____

Previous Survey: Reference: Notes:
 H.A.B.S. Other.. _____
 Feiss-Wright (1969) _____
 Historic Resources of the Lowcountry (1979) _____
 Milner Historic District Inventory (1979) _____
 A Guide to Historic Beaufort (1995 ed.) _____

Photograph:



Photographs:

- prints
- slides
- negatives

Date: 9/11/97
Recorder: B. Harvey, Brockington & Assoc.

Roll # Neg. View of:
H-20 11 ne oblique

Style: Folk: massed-plan, side gabled Commercial Form: _____

Core Shape: _____ Stories: _____ Construction: _____

Roof: Shape: gable (lateral) Material: composition shingle

Chimney: Type: flue Material: brick

Exterior Walls: weatherboard

Windows: single Type: double hung Pane 6/6
 Config.: _____

Doors: single Foundation: not visible

Porch Height: _____ Porch Width: _____ Porch Roof Shape: _____

Porch Details: _____ Decorative Elements: _____

Outbuildings: _____ Interior Features: _____

Number of Related Resources: 10


Surroundings: Plantation complex Acreage: _____ Quadrangle: Sheldon

Alterations: Alteration date: _____ Integrity: good Condition: good

Description: Small house adjacent to main house. No clear front entrance; single wooden door on small cross gable extension.

Historical Data: Part of Tomotley Plantation complex, recreated by R.L. McCurdy in c. 1910.

Sketch:



Site Number: U - 13 - 481.07

Informant/
Bibliography: