

**BEAUFORT COUNTY
HISTORIC SITES SURVEY - 1997**

INTENSIVE LEVEL BUILDING INVENTORY FORM

Statewide Survey Site Form
State Historic Preservation Office
South Carolina Department of Archives and History
Columbia, SC

Site Number: U- 13 - 482.04
Access County Site #

USGS Quad: 569 Yemassee
Doc. Level: Intensive Level-Building

Historic name(s): Twickenham Plantation Map Ref.: _____ Tax Number: R800 024 000 0121 0000
Common name(s): Twickenham Plantation City Block Ref.: _____ Island: _____
Address/location: off River Road City/Vicinity of (vic.) Yemassee vic.
Date: 1930 ca. Alteration date: _____
Ownership: 1. private 2. city 3. county 4. state 5. federal 6. unknown
Category: 1. building 2. site 3. structure 4. object
Historic use(s): stables Current uses: stables

National Register Status: _____ Date: _____ Listing Name: _____ NRIS # _____

SHPO Determination: District: Contributing Non-contributing Potential: National Register District, Contributing

Consultant Recommendation: _____

Previous Survey: _____ Reference: _____ Notes: _____
 H.A.B.S. Other.. _____
 Feiss-Wright (1969) _____
 Historic Resources of the Lowcountry (1979) _____
 Milner Historic District Inventory (1979) _____
 A Guide to Historic Beaufort (1995 ed.) _____

Photograph:



Photographs:

- prints
- slides
- negatives

Date: 9/11/97
Recorder: B. Harvey, Brockington & Assoc.

Roll # Neg. View of:
H-21 5 sw oblique

Style: _____ Commercial Form: _____

Core Shape: rectangular Stories: 1 story Construction: frame

Roof: Shape: gable (lateral) Material: raised seam metal

Chimney: Type: _____ Material: _____

Exterior Walls: weatherboard

Windows: double Type: fixed Pane 9 pane
 Config.: _____

Doors: 5 stable double doors Foundation: slab construction

Porch Height: 1 story Porch Width: full facade Porch Roof Shape: recessed

Porch Details: posts Decorative Elements: _____

Outbuildings: _____ Interior Features: _____

Number of Related Resources: 8


Surroundings: part of plantation complex Acreage: _____ Quadrangle: Yemassee

Alterations: Alteration date: _____ Integrity: good Condition: good

Description: Five-bay side gable stable. Front roof sweeps out to form porch over the stable doors. The left end of the porch has been enclosed to form one room.

Historical Data: Part of Twickenham Plantation complex, apparently built during 1930 restoration

Sketch:



Site Number: U - 13 - 482.04

Informant/
Bibliography: