

**BEAUFORT COUNTY
HISTORIC SITES SURVEY - 1997**

INTENSIVE LEVEL BUILDING INVENTORY FORM

Statewide Survey Site Form
State Historic Preservation Office
South Carolina Department of Archives and History
Columbia, SC

Site Number: U- 13 - 482.05
Access County Site #
USGS Quad: 569 Yemassee
Doc. Level: Intensive Level-Building

Historic name(s): Twickenham Plantation Map Ref.: _____ Tax Number: R800 024 000 0121 0000
Common name(s): Twickenham Plantation City Block Ref.: _____ Island: _____
Address/location: off River Road City/Vicinity of (vic.): Yemassee vic.
Date: 1930 ca. Alteration date: _____
Ownership: 1. private 2. city 3. county 4. state 5. federal 6. unknown
Category: 1. building 2. site 3. structure 4. object
Historic use(s): barn Current uses: barn


National Register Status: _____ Date: _____ Listing Name: _____ NRIS # _____

SHPO Determination: District: Contributing Non-contributing Potential: National Register District, Contributing

Consultant Recommendation: _____

Previous Survey:	Reference:	Notes:
<input type="checkbox"/> H.A.B.S.	<input type="checkbox"/> Other.. _____	_____
<input type="checkbox"/> Feiss-Wright (1969)	_____	_____
<input type="checkbox"/> Historic Resources of the Lowcountry (1979)	_____	_____
<input type="checkbox"/> Milner Historic District Inventory (1979)	_____	_____
<input type="checkbox"/> A Guide to Historic Beaufort (1995 ed.)	_____	_____

Photograph:



Photographs:
 prints
 slides
 negatives

Date: 9/11/97
Recorder: B. Harvey, Brockington & Assoc.

Roll #	Neg.	View of:
<u>H-21</u>	<u>6</u>	<u>nw oblique</u>
_____	_____	_____
_____	_____	_____
_____	_____	_____

Style: _____ Commercial Form: _____

Core Shape: rectangular Stories: 1.5 stories Construction: frame

Roof: Shape: gable (lateral) Material: raised seam metal

Chimney: Type: _____ Material: _____

Exterior Walls: weatherboard

Windows: _____ Type: _____ Pane Config.: _____

Doors: 3 barn doors Foundation: slab construction

Porch Height: _____ Porch Width: _____ Porch Roof Shape: _____

Porch Details: _____ Decorative Elements: _____

Outbuildings: _____ Interior Features: _____

Number of Related Resources: 8


Surroundings: part of plantation complex Acreage: _____ Quadrangle: Yemassee

Alterations: Alteration date: _____ Integrity: good Condition: good

Description: Long rectangular barn with 3 off-center double barn doors. Side gable features a wood casement window.

Historical Data: Part of Twickenham Plantation complex, apparently built during 1930 restoration

Sketch:



Site Number: U - 13 - 482.05

Informant/
Bibliography: