

**BEAUFORT COUNTY
HISTORIC SITES SURVEY - 1997**

INTENSIVE LEVEL BUILDING INVENTORY FORM

Statewide Survey Site Form
State Historic Preservation Office
South Carolina Department of Archives and History
Columbia, SC

Site Number: U- 13 - 504
Access County Site #
USGS Quad: 025 Beaufort
Doc. Level: Intensive Level-Building

Historic name(s): _____ Map Ref.: PR 11 Tax Number: R110 010 000 0181 0000
Common name(s): _____ City Block Ref.: _____ Island: Port Royal Is.
Address/location: 707 Paris Ave. City/Vicinity of (vic.) Port Royal
Date: 1935 ca. Alteration date: _____
Ownership: 1. private 2. city 3. county 4. state 5. federal 6. unknown
Category: 1. building 2. site 3. structure 4. object
Historic use(s): commercial Current uses: commercial

National Register Status: _____ Date: _____ Listing Name: _____ NRIS # _____

SHPO National Register Evaluation: _____ Name: _____

Consultant Recommendation: Contributes to potential local district Name: Port Royal Historic District

Previous Survey: _____ Reference: _____ Notes: _____
 H.A.B.S. Other _____
 Feiss-Wright (1969) _____
 Historic Resources of the Lowcountry (1979) _____
 Milner Historic District Inventory (1979) _____
 A Guide to Historic Beaufort (1995 ed.) _____

Photograph:



Photographs:

- prints
- slides
- negatives

Date: 3/9/98

Recorder: D. Schneider, Historic Beaufort Fdn.

Roll # Neg. View of:
B-23 1 E facade, fac. W

Style: _____ Commercial Form: _____

Core Shape: rectangular _____ Stories: _____ Construction: frame _____
 Roof: Shape: gable (lateral) _____ Material: composition shingle _____

Chimney: Type: not visible _____ Material: brick _____
 flue _____

Exterior Walls: weatherboard _____

Windows: single _____ Type: double hung _____ Pane 6/6 _____
 double _____ Config.: _____

Doors: single _____ Foundation: brick piers _____

Porch Height: 1 story _____ Porch Width: entrance bay only _____ Porch Roof Shape: gable _____
 Porch Details: brackets _____ Decorative Elements: _____

Outbuildings: none _____ Interior Features: _____


Number of Related Resources: _____

Surroundings: commercial, urban _____ Acreage: _____ Quadrangle: Beaufort _____

Alterations: Alteration date: _____ Integrity: excellent _____ Condition: good _____
 An aluminum storm door at the entrance represents the only exterior alteration.

Description: Rectangular 3 x 1 bay commercial building w/lateral gable composition shingle roof. Exposed rafter ends at eaves. East facade has central entrance flanked by double 6/6 double hung windows. Entrance has a entrance bay only gable awning supported by triangular wood brackets. Side elevations have single 6/6 windows and small rectangular louvered attic vents within their gables. Rear elevation has no openings and an exterior brick flue.

Historical Data: This building is not shown on the 1924 Sanborn map; an earlier 1-story store building is shown.



Site Number: U - 13 - 504