

**BEAUFORT COUNTY
HISTORIC SITES SURVEY - 1997**

INTENSIVE LEVEL BUILDING INVENTORY FORM

Statewide Survey Site Form
 State Historic Preservation Office
 South Carolina Department of Archives and History
 Columbia, SC

Site Number: U- 13 - 506
Access County Site #
 USGS Quad: 025 Beaufort
 Doc. Level: Intensive Level-Building

Historic name(s): _____ Map Ref.: PR 12 Tax Number: R110 011 000 0072 0000
 Common name(s): _____ City Block Ref.: _____ Island: Port Royal Is.
 Address/location: 910 7th St. City/Vicinity of (vic.) Port Royal
 Date: 1922 Alteration date: 1980 ca.
 Ownership: 1. private 2. city 3. county 4. state 5. federal 6. unknown
 Category: 1. building 2. site 3. structure 4. object
 Historic use(s): single dwelling Current uses: single dwelling

National Register Status: _____ Date: _____ Listing Name: _____ NRIS # _____

SHPO National Register Evaluation: _____ Name: _____

Consultant Recommendation: Contributes to potential local district Name: Port Royal Historic District

Previous Survey: _____ Reference: _____ Notes: _____
 H.A.B.S. Other _____
 Feiss-Wright (1969) _____
 Historic Resources of the Lowcountry (1979) _____
 Milner Historic District Inventory (1979) _____
 A Guide to Historic Beaufort (1995 ed.) _____

Photograph:



Photographs:

- prints
- slides
- negatives

Date: 7/1/97

Recorder: D. Schneider, Historic Beaufort Fdn.

Roll # Neg. View of:
 B-08 11 S facade & w elev., fac. NE

Style: Folk: gable front Commercial Form: _____

Core Shape: rectangular Stories: 1.5 stories Construction: frame
 Roof: Shape: jerkin head Material: pressed metal shingle

Chimney: Type: interior Material: brick

Exterior Walls: weatherboard

Windows: double single Type: double hung Pane 6/6
 Config.: _____

Doors: single Foundation: brick piers

Porch Height: 1 story Porch Width: full facade Porch Roof Shape: shed
 Porch Details: posts Decorative
 slat balusters Elements: _____

Outbuildings: none Interior
 Features: _____


Number of Related Resources: _____

Surroundings: residential Acreage: _____ Quadrangle: Beaufort

Alterations: Alteration date: 1980 ca. Integrity: good Condition: good
 Storm windows, replacement porch, stuccoed masonry foundation infill.

Description: Rectangular 1.5 story 3 x 3 bay frame dwelling w/front-facing jerkin head roof; 2 1 bay deep frame additions at rear. Patterned metal shingle roof. Central entrance at facade flanked by double 6/6 double hung sash windows. Single 6/6 windows at gable end and at side elevs.

Historical Data: Shown on 1924 Sanborn map; date from assessor's office



Site Number: U - 13 - 506

Informant/ Bibliography: Sanborn maps. County assessor's records.