

**BEAUFORT COUNTY
HISTORIC SITES SURVEY - 1997**

INTENSIVE LEVEL BUILDING INVENTORY FORM

Statewide Survey Site Form
State Historic Preservation Office
North Carolina Department of Archives and History
Columbia, SC

Site Number: U- 13 - 524
Access County Site #
USGS Quad: 025 Beaufort
Doc. Level: Intensive Level-Building

Historic name(s): _____ Map Ref.: PR 12 Tax Number: R110 011 000 0046 0000
Common name(s): _____ City Block Ref.: _____ Island: Port Royal Is.
Address/location: 903 London Ave. City/Vicinity of (vic.): Port Royal
Date: 1920 ca. Alteration date: 1980 ca.
Ownership: 1. private 2. city 3. county 4. state 5. federal 6. unknown
Category: 1. building 2. site 3. structure 4. object
Historic use(s): single dwelling Current uses: single dwelling

National Register Status: _____ Date: _____ Listing Name: _____ NRIS # _____

SHPO National Register Evaluation: _____ Name: _____

Consultant Recommendation: Contributes to potential local district Name: Port Royal Historic District

Previous Survey: _____ Reference: _____ Notes: _____
 H.A.B.S. Other _____
 Feiss-Wright (1969) _____
 Historic Resources of the Lowcountry (1979) _____
 Milner Historic District Inventory (1979) _____
 A Guide to Historic Beaufort (1995 ed.) _____

Photograph:



Photographs:

- prints
- slides
- negatives

Date: 7/1/97

Recorder: D. Schneider, Historic Beaufort Fdn.

Roll # Neg. View of:
B-08 29 E facade & N elev., fac. SW

Style: Folk: gable front Commercial Form: _____

Core Shape: rectangular Stories: 2 stories Construction: frame
 Roof: Shape: gable (end to front) Material: composition shingle

Chimney: Type: interior Material: stuccoed brick

Exterior Walls: weatherboard

Windows: single Type: double hung Pane 6/6
 Config.: _____

Doors: single Foundation: brick piers
 transom
 sidelights

Porch Height: 2 or more stories Porch Width: full facade Porch Roof Shape: shed
 Porch Details: chamfered posts Decorative Elements:
 slat balusters

Outbuildings: none Interior Features: _____

Number of Related Resources: _____

Surroundings: residential Acreage: _____ Quadrangle: Beaufort

Alterations: Alteration date: 1980 ca. Integrity: good Condition: good
 Porch railings, addition.

Description: Rectangular 2 story frame 3 x 2 bay dwelling w/front-facing gable roof; rear 3 x 2 bay addition. Two story porch with shed roof retains chamfered posts and has recent slat balustrade. Principal entrance at N bay of facade has transom. Two southern bays have 6/6 double hung sash windows. Similar fenestration at 2nd level except that door has no transom. 6/6 windows at side elevs.

Historical Data: The building is shown on the 1924 Sanborn map. Assessor's office lists date of construction as 1920.

Sketch:



Site Number: U - 13 - 524

Informant/
 Bibliography: