

**BEAUFORT COUNTY
HISTORIC SITES SURVEY - 1997**

INTENSIVE LEVEL BUILDING INVENTORY FORM

Statewide Survey Site Form
State Historic Preservation Office
South Carolina Department of Archives and History
Columbia, SC

Site Number: U- 13 - 532
Access County Site #
USGS Quad: 025 Beaufort
Doc. Level: Intensive Level-Building

Historic name(s): _____ Map Ref.: PR 12 Tax Number: R110 011 000 0035 0000
Common name(s): _____ City Block Ref.: _____ Island: Port Royal Is.
Address/location: 911 11th St. City/Vicinity of (vic.): Port Royal
Date: 1920 ca. Alteration date: 1970 ca.
Ownership: 1. private 2. city 3. county 4. state 5. federal 6. unknown
Category: 1. building 2. site 3. structure 4. object
Historic use(s): single dwelling Current uses: single dwelling

National Register Status: _____ Date: _____ Listing Name: _____ NRIS # _____

SHPO National Register Evaluation: _____ Name: _____

Consultant Recommendation: Contributes to potential local district Name: Port Royal Historic District

Previous Survey: _____ Reference: _____ Notes: _____
 H.A.B.S. Other _____
 Feiss-Wright (1969) _____
 Historic Resources of the Lowcountry (1979) _____
 Milner Historic District Inventory (1979) _____
 A Guide to Historic Beaufort (1995 ed.) _____

Photograph: _____



Photographs:

- prints
- slides
- negatives

Date: 5/13/97

Recorder: D. Schneider, Historic Beaufort Fdn.


Roll # Neg. View of:
B-09 2 N & E elevs., fac. SW

Style: Folk: hall-and-parlor Commercial Form: _____
 Core Shape: rectangular Stories: 1 story Construction: frame
 Roof: Shape: gable (lateral) Material: V crimp metal
 Chimney: Type: not visible Material: _____
 Exterior Walls: weatherboard
 Windows: single Type: double hung Pane 6/6
 Config.: replacement synthetic
 Doors: single Foundation: brick piers
 Porch Height: 1 story Porch Width: full facade Porch Roof Shape: shed
 Porch Details: apron wall Insect screening Decorative Elements: _____
 Outbuildings: Interior Features: _____
 Number of Related Resources: _____
 Surroundings: residential Acreage: _____ Quadrangle: Beaufort
 Alterations: Alteration date: 1970 ca. Integrity: fair Condition: good
 porch screening, apron wall and roof framing

Description: Rectangular 1 story 3 x 1 bay frame dwelling w/rear shed addition; pedimented gable ends

Historical Data: Shown on 1924 Sanborn map; area not included on earlier maps

Sketch:



Site Number: U - 13 - 532

Informant/
Bibliography: