

**BEAUFORT COUNTY
HISTORIC SITES SURVEY - 1997**

INTENSIVE LEVEL BUILDING INVENTORY FORM

Statewide Survey Site Form
State Historic Preservation Office
South Carolina Department of Archives and History
Columbia, SC

Site Number: U- 13 - 533
Access County Site #
USGS Quad: 025 Beaufort
Doc. Level: Intensive Level-Building

Historic name(s): _____ Map Ref.: PR 12 Tax Number: R110 011 000 0032 0000
Common name(s): _____ City Block Ref.: _____ Island: Port Royal Is.
Address/location: 909 11th St. City/Vicinity of (vic.): Port Royal
Date: 1920 Alteration date: _____
Ownership: 1. private 2. city 3. county 4. state 5. federal 6. unknown
Category: 1. building 2. site 3. structure 4. object
Historic use(s): single dwelling Current uses: single dwelling

National Register Status: _____ Date: _____ Listing Name: _____ NRIS # _____

SHPO National Register Evaluation: _____ Name: _____

Consultant Recommendation: Contributes to potential local district Name: Port Royal Historic District

Previous Survey: _____ Reference: _____ Notes: _____
 H.A.B.S. Other _____
 Feiss-Wright (1969) _____
 Historic Resources of the Lowcountry (1979) _____
 Milner Historic District Inventory (1979) _____
 A Guide to Historic Beaufort (1995 ed.) _____

Photograph:



Photographs:
 prints
 slides
 negatives

Date: 5/13/97

Recorder: D. Schneider, Historic Beaufort Fdn.

Roll # Neg. View of:
B-09 3 W & S elevs., fac. NE

Style: Folk: gable front Commercial Form: _____

Core Shape: rectangular Stories: 1.5 stories Construction: frame

Roof: Shape: gable (end to front) Material: V crimp metal

Chimney: Type: interior Material: brick

Exterior Walls: weatherboard

Windows: single Type: double hung Pane 6/6
double Config.: _____

Doors: single Foundation: brick piers

Porch Height: 1 story Porch Width: full facade Porch Roof Shape: shed

Porch Details: posts Decorative Elements: _____

Outbuildings: Interior Features: _____

Number of Related Resources: _____


Surroundings: residential Acreage: _____ Quadrangle: Beaufort

Alterations: Alteration date: _____ Integrity: good Condition: good

Description: Rectangular 1.5 story frame 3 x 2 bay dwelling w/front facing gable roof; single windows at facade, double at side elevs. ; housed sills

Historical Data: Shown on 1924 Sanborn map; area not included on earlier maps

Sketch:



Site Number: U - 13 - 533

Informant/
Bibliography: