

**BEAUFORT COUNTY  
HISTORIC SITES SURVEY - 1997**

INTENSIVE LEVEL BUILDING INVENTORY FORM

Statewide Survey Site Form  
State Historic Preservation Office  
South Carolina Department of Archives and History  
Columbia, SC

Site Number: U- 13 - 544  
Access County Site #

USGS Quad: 025 Beaufort  
Doc. Level: Intensive Level-Building

Historic name(s): \_\_\_\_\_ Map Ref.: PR 12 Tax Number: R110 011 000 0025 0000  
Common name(s): \_\_\_\_\_ City Block Ref.: \_\_\_\_\_ Island: Port Royal Is.  
Address/location: 917 12th St. City/Vicinity of (vic.) Port Royal  
Date: 1925 ca. Alteration date: 1960 ca.  
Ownership:  1. private  2. city  3. county  4. state  5. federal  6. unknown  
Category:  1. building  2. site  3. structure  4. object  
Historic use(s): single dwelling Current uses: single dwelling

National Register Status: \_\_\_\_\_ Date: \_\_\_\_\_ Listing Name: \_\_\_\_\_ NRIS # \_\_\_\_\_

SHPO National Register Evaluation: \_\_\_\_\_ Name: \_\_\_\_\_

Consultant Recommendation: Contributes to potential local district Name: Port Royal Historic District

Previous Survey: \_\_\_\_\_ Reference: \_\_\_\_\_ Notes: \_\_\_\_\_  
 H.A.B.S.  Other \_\_\_\_\_  
 Feiss-Wright (1969) \_\_\_\_\_  
 Historic Resources of the Lowcountry (1979) \_\_\_\_\_  
 Milner Historic District Inventory (1979) \_\_\_\_\_  
 A Guide to Historic Beaufort (1995 ed.) \_\_\_\_\_

Photograph:



Photographs:

- prints
- slides
- negatives

Date: 5/13/97

Recorder: D. Schneider, Historic Beaufort Fdn.

Roll # Neg. View of:  
B-09 7 N & W elev., fac. SE




Style: Folk: gable front Commercial Form: \_\_\_\_\_  
 Core Shape: rectangular Stories: 1 story Construction: frame  
 Roof: Shape: gable (end to front) Material: composition shingle  
 Chimney: Type: interior Material: brick  
 Exterior Walls: asbestos shingle  
 Windows: single Type: double hung Pane 6/6  
 Config.: \_\_\_\_\_  
 Doors: single Foundation: brick piers  
 Porch Height: 1 story Porch Width: entrance bay only Porch Roof Shape: gable  
 Porch Details: posts Decorative Elements: \_\_\_\_\_  
 Outbuildings: Interior Features: \_\_\_\_\_  
 Number of Related Resources: \_\_\_\_\_  
 Surroundings: residential Acreage: \_\_\_\_\_ Quadrangle: Beaufort  
 Alterations: Alteration date: 1960 ca. Integrity: good Condition: good  
 asbestos siding

Description: rectangular 1 story frame dwelling w/front facing gable roof; exposed rafter ends; tapered posts

Historical Data: Not shown on 1924 Sanborn Map

Sketch:



Site Number: U - 13 - 544

Informant/  
Bibliography: